

IECEX BAS 16.0076X issue: 0 IECEX CML 18.0197X issue: 2 -- Continued on the next page

IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION

IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/BAS/QAR06.	0017/11	Page 1 of 2
QAR Free Ref. No.:	1112		Status: Issued
Details of change:	Surveillance audit	completed	Date of issue:2023-01-11
Location(s) audited:	The Wolf Safety Lamp Co. Limited		Valid until: 2024-06-08
	Saxon Road Work Sheffield S8 0YA United Kingdom	(S	Audit date: 2022-11-28
Issuing ExCB:	BAS - SGS Base	efa Limited	
Manufacturer:	The Wolf Safety Saxon Road Work Sheffield S8 0YA	Lamp Co. Limited s	
Location of Manufacturer:	United Kingdom		
Product information:	Torches, Luminair	es, lamps	
Type of protection:	Ex 'd' 'e' 'i' 'm' 't' 'op is' 's'		
Related QARs:			
GB/BAS/QAR06.0017/00 GB/BAS/QAR06.0017/03 GB/BAS/QAR06.0017/06 GB/BAS/QAR06.0017/09		GB/BAS/QAR06.0017/01 GB/BAS/QAR06.0017/04 GB/BAS/QAR06.0017/07 GB/BAS/QAR06.0017/10	GB/BAS/QAR06.0017/02 GB/BAS/QAR06.0017/05 GB/BAS/QAR06.0017/08
Related Certificates	(manual insertion)::		
IECEx TSA 05.0017	x		
Related Certificates	(automatic linking)::		
IECEx CML 22.0083	X issue: 0		
Related Certificates to previous versions:	for		
IECEX BAS 06.0001 IECEX BAS 06.0001 IECEX BAS 06.0001 IECEX BAS 06.0023 IECEX BAS 06.0023 IECEX BAS 06.0023 IECEX BAS 06.0023 IECEX BAS 06.0089 IECEX BAS 06.0089 IECEX BAS 09.0153 IECEX BAS 09.0153 IECEX BAS 09.0153 IECEX BAS 09.0153 IECEX BAS 10.0023 IECEX BAS 10.0023 IECEX BAS 11.0116 IECEX BAS 15.0033	issue: 4 issue: 10 X issue: 8 issue: 2 issue: 8 X issue: 6 issue: 1 issue: 7 X issue: 6 issue: 2 X issue: 4 X issue: 7 issue: 2 X issue: 4 issue: 4 K issue: 3	IECEx BAS 06.0001 issue: 2 IECEx BAS 06.0001 issue: 5 IECEX BAS 06.001X issue: 6 IECEX BAS 06.0023 issue: 0 IECEX BAS 06.0023 issue: 3 IECEX BAS 06.0023 issue: 9 IECEX BAS 06.0023X issue: 7 IECEX BAS 06.0089X issue: 7 IECEX BAS 06.0089X issue: 2 IECEX BAS 09.0153 issue: 0 IECEX BAS 09.0153X issue: 3 IECEX BAS 09.0153X issue: 5 IECEX BAS 10.0023 issue: 0 IECEX BAS 11.0116 issue: 5 IECEX BAS 11.0116 issue: 5 IECEX BAS 14.0095 issue: 0 IECEX BAS 15.0033X issue: 1	IECEx BAS 06.0001 issue: 3 IECEx BAS 06.0001 issue: 9 IECEx BAS 06.0001 issue: 7 IECEx BAS 06.0023 issue: 7 IECEx BAS 06.0023 issue: 1 IECEx BAS 06.0023 issue: 4 IECEx BAS 06.0089 issue: 5 IECEx BAS 06.0089 issue: 0 IECEx BAS 06.0089 issue: 3 IECEx BAS 06.0089 issue: 3 IECEx BAS 09.0153 issue: 1 IECEx BAS 09.0153 issue: 6 IECEx BAS 09.0153X issue: 6 IECEx BAS 10.0023X issue: 3 IECEx BAS 11.0116 issue: 1 IECEX BAS 11.0116X issue: 2 IECEX BAS 15.0033X issue: 2
IECEX BAS 16.0073	X issue: 0	IECEX BAS 16.0073X issue: 1	IECEX BAS 16.0076 issue: 1

IECEX CML 18.0197X issue: 0 IECEX CML 18.0198X issue: 0

IECEx CML 18.0197X issue: 1 IECEx CML 18.0198X issue: 1



IECEx Quality Assessment Report Summary

QAR Ref. No.:

GB/BAS/QAR06.0017/11

Page 2 of 2

Related Certificates for previous versions (continued):

IECEx CML 18.0198X issue: 2
IECEx CML 18.0199X issue: 2
IECEx EXV 18.0027U issue: 1
IECEx EXV 19.0001X issue: 1
IECEx EXV 19.0072U issue: 0
IECEx EXV 19.0079X issue: 0
IECEx SIR 10.0016X issue: 1
IECEx SIR 10.0016X issue: 4
IECEx SIR 10.0121 issue: 1
IECEx SIR 12.0070X issue: 0
IECEx SIR 12.0070X issue: 3
IECEx SIR 12.0070X issue: 6
IECEx SIR 15.0115X issue: 0
IECEx SIR 17.0013X issue: 1

Comments:

IECEX CML 18.0199X issue: 0 IECEX CML 19.0005X issue: 0 IECEX EXV 18.0027U issue: 2 IECEX EXV 19.0002X issue: 0 IECEX EXV 19.0073U issue: 0 IECEX EXV 19.0079X issue: 1 IECEX SIR 10.0016X issue: 2 IECEX SIR 10.016X issue: 5 IECEX SIR 10.0121X issue: 2 IECEX SIR 12.0070X issue: 1 IECEX SIR 12.0070X issue: 4 IECEX SIR 12.0070X issue: 7 IECEX SIR 15.0115X issue: 1 IECEX SIR 18.0028X issue: 0 IECEX CML 18.0199X issue: 1 IECEX EXV 18.0027U issue: 0 IECEX EXV 19.0001X issue: 0 IECEX EXV 19.0002X issue: 1 IECEX SIR 10.0016X issue: 0 IECEX SIR 10.0016X issue: 3 IECEX SIR 10.0121 issue: 0 IECEX SIR 10.0121X issue: 3 IECEX SIR 12.0070X issue: 2 IECEX SIR 12.0070X issue: 5 IECEX SIR 12.0070X issue: 5 IECEX SIR 12.0070X issue: 8 IECEX SIR 17.0013X issue: 0